

Crosstown LRT Project – Update, May 18, 2018

- Monitoring results show that there was no significant increase in dust or noise levels in the last two weeks.
- The newly erected scaffolding with sound absorbing panels appears to be effective in attenuating noise in the north-west side of the school. Please see [Pictures](#) section online.
- We'll continue monitoring dust and noise levels on the regular basis.
- Phase 2: As an additional safety measure, Plexiglas will be installed on the windows located on the north-east side by the end of May.

Please visit the [school](#) and [Crosstown LRT](#) websites for regular updates.